


WindowMaster - ceramic plug and cables  
 WindowMaster - keramisk stik og ledninger  
 WindowMaster - keramisk kontakt och ledningar  
 WindowMaster - keramische Stecker und Kabel

Smoke ventilation,  
one motor:


Røgventilation,  
en motor:

Rökventilation,  
en motor:

Rauchventilation,  
ein Motor:



1. First open the window, then disconnect the chain (4x20 US screw):



2. To reconnect the chain, power the chain out to meet the sash.

Smoke ventilation,  
more motors:

Røgventilation, flere  
motorer:

Rökventilation, flera  
motorer:

Rauchventilation,  
synchronisierte  
Motoren:

